

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 15103-36-535 State Number 11639

1

		EQUIPMENT INSPECTED			
State Number: 11639 Capacity: 2500	Type of Unit: Pas Manuf: THYSSE	=	Floor to Floor: 1 Speed: 125	to 3	
Landings: 3	Installed: 03/06/1	986	Rope Size:		
Volts: 200	Complied: 03/06/1986		Entrances: 1		
OWNER		OCCUPANT			
CAROLINA BIOLOGICAL SUPI	PLY		BIOLOGICAL SUPP.		
ATTN ACCOUNTS PAYABLE	1308 RAINE		ST		
BURLINGTON, NC, 27216-6005		BURLINGTO	BURLINGTON, NC, 27215		
	IN:	SPECTION INFORMATION			
Inspection Date 04/13/2015	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE	
		VIOLATIONS			
none found					
Notify the Elevator Bureau in writin omplainace with current codes.	g on Corrected Violations Form	when the following corrections	have been made in order to bring	g your equipment into	
iolations pointed out to: Glenn Wa			Inspector		
	o make changes to the invoice ma	ailing address please call: 919-7			
THIS IS NOT AN	CAROLINA BIOLOGICAL SUPPLY				
INVOICE A	n invoice will be mailed to:	ATTN ACCOUNTS PA' BURLINGTON, NC, 27	YABLE		