



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
15104-48-549
State Number
6961

EQUIPMENT INSPECTED

State Number: 6961	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2000	Manuf: OTIS	Speed: 100
Landings: 2	Installed: 08/05/1971	Rope Size:
Volts: 480	Complied: 08/05/1971	Entrances: 1
OWNER	OCCUPANT	
ELIZABETHTOWN MIDDLE SCHOOL	ELIZABETHTOWN MIDDLE SCHOOL	
P O BOX 2519	HWY 701 SOUTH	
ELIZABETHTOWN, NC, 28327	ELIZABETHTOWN, NC, 28337	

INSPECTION INFORMATION

Inspection Date 04/14/2015	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BLADEN
-------------------------------	----------------------------	---------------------------------	--------------------------	------------------

9

VIOLATIONS

- 3.24.1 Elevator pumping unit. [REMOVE OIL FROM UNDER UNIT] [SAME AS LAST YR.]
- 2.2.5.1 Put the pit lights in proper working order.

Items must be corrected by: 05/14/2015

Elevator Name: # 1

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: DIANNE

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ELIZABETHTOWN MIDDLE SCHOOL
P O BOX 2519
ELIZABETHTOWN, NC, 28327