

INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
www.nclabor.com/elevator.htm  
919-807-2770

Report Number <b>15111-36-0829</b> State Number <b>N1.44</b>
---

EQUIPMENT INSPECTED

State Number: <b>N1.44</b>	Type of Unit: Freight	Floor to Floor: to
Capacity: 1200	Manuf: MOFFAT	Speed: 75
Landings: 3	Installed: 04/30/1928	Rope Size: 1/2
Volts:	Complied: 04/30/1928	Entrances:
OWNER	OCCUPANT	
BURLINGTON DRAPERY CO	BURLINGTON DRAPERY CO	
227 UNION AVE.	227 UNION AVE.	
BURLINGTON, NC, 27215	BURLINGTON, NC, 27215	

INSPECTION INFORMATION

Inspection Date 04/21/2015	Type Inspection Not Inspected	Certificate Status Not Issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------------	----------------------------------	---------------------------	--------------------

1

VIOLATIONS

left message with donnie harrison to call and set up inspection

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: n/a

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

BURLINGTON DRAPERY CO  
227 UNION AVE.  
BURLINGTON, NC, 27215