NCDOL NCDOL N. Department of labor

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 15126-48-559
State Number 23293

		EQUIPMENT INSPECTED			
State Number: 23293 Type of Unit: Pa		Passenger	ger Floor to Floor: 1 to 3		
Capacity: 2100 Manuf: OTIS			Speed: 100		
Landings: 3 Installed: 09/12/20 Volts: 208 Complied: 09/12/2 OWNER COMMUNITY ASSOCIATION MGMT. P.O. BOX 8126		12/2005	1		
		0/12/2005			
		OCC	OCCUPANT VILLAS ON OSPREY RIDGE		
		VIL			
		178	CLUB HOUSE RD		
OCEAN ISLE, NC, 28469		SUN	SUNSET BEACH, NC, 28468		
	п	NSPECTION INFORMATION	[
Inspection Date 05/06/2015	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK	
		VIOLATIONS			
Items must be corrected by: Notify the Elevator Bureau in w complainace with current codes. Violations pointed out to: UNA	riting on Corrected Violations Form	n when the following correction	_	bring your equipment into	
*					
To make changes to the invoice mailing address please call: 919-733-0372 THIS IS NOT AN INVOICE An invoice will be mailed to: P.O. BOX 8126 OCEAN ISLE, NC, 28469			CIATION MGMT.		