

THIS IS NOT AN

INVOICE

An invoice will be mailed to:

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number **15131-36-5034** State Number **14232**

1

	EG	QUIPMENT INSPECTED		
State Number: 14232	Type of Unit: Passe	enger	Floor to Floor:	B to 3
Capacity: 4000	Manuf: THYSSEN	KRUPP	Speed: 125	
Landings: 4 Installed: 08/22/1991		91	Rope Size:	
Volts: 460	Complied: 08/22/19	991	Entrances: 1	
OWNER		OCCUPA	NT	
KOURY PROPERTIES CENTE	ER	KOURY MANANGMENT		
PO BOX 850		3060 S CHURCH ST		
BURLINGTON, NC, 27215		BURLINGTON, NC, 27215		
	INS	PECTION INFORMATION		
Inspection Date 05/11/2015	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
THIS UNIT IS IN COMPLIAN	ICE THIS DATE 5-11-2015	VIOLATIONS		
THIS UNIT IS IN COMPLIAN	ICE THIS DATE 5-11-2015	VIOLATIONS		
	ting on Corrected Violations Form w		nave been made in order to bri	ng your equipment into

PO BOX 850

KOURY PROPERTIES CENTER

BURLINGTON, NC, 27215