NCDOL NCDOL

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 15169-48-324 State Number H2361

	EQ	UIPMENT INSPECTED		
State Number: H2361	Type of Unit: Ha		Floor to Floor: 1 to 2	
Capacity: 750	Manuf: GARAV Installed: 03/06/2		Speed: 17	
Landings: 2 Volts: 120	Complied: 03/06/2	2012	Rope Size: Entrances: 2	
	Complica.	O COLTRA NET	Entrances. 2	
OWNER	NE EDUCATION	OCCUPANT BLADENBOROA	AIDDI E HICH SCHOOL	
BLADEN COUNTY BOARD OF EDUCATION P O BOX 2519		BLADENBORO MIDDLE HIGH SCHOOL 910 S MAIN STREET		
ELIZABETHTOWN, NC, 28337		BLADENBORO, NC, 28320		
	INSP	ECTION INFORMATION		
Inspection Date 06/18/2015	Type Inspection Compliance	Certificate Status Prev Issued	Inspector 48 - Martin	County BLADEN
		VIOLATIONS		
Elevator Name: #1				
otify the Elevator Bureau in writ	ing on Corrected Violations Form wh	en the following corrections have	been made in order to bring yo	our equipment into
iolations pointed out to: MGMT		Inspector		
	To make changes to the invoice mailing address please call: 919-733-0372			
THIS IS NOT AN INVOICE	BLADEN COUNTY BOARD OF EDUCATION An invoice will be mailed to: P O BOX 2519 FLIZABETHTOWN NC 28337			