

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 15169-48-5236 State Number H1672

EQUIPMENT INSPECTED				
State Number: H1672 Capacity: 750 Landings: 2 Volts: 240 OWNER FIRST BAPTIST CHURCH PO BOX 176 BLADENBORO, NC, 28320	Type of Unit: H Manuf: GARAV Installed: 11/01/ Complied: 11/01	ZENTA 2005	•	
	INSP	ECTION INFORMATION		
Inspection Date 06/18/2015	Type Inspection Not Inspected	Certificate Status Not Issued	Inspector 48 - Martin	County BLADEN
		VIOLATIONS		
complainace with current codes Violations pointed out to: UNA	AVAILABLE		Inspector	
	To make changes to the invoice mailing address please call: 919-733-0372			
THIS IS NOT AN INVOICE	An invoice will be mailed to:	FIRST BAPTIST CHURCH PO BOX 176 BLADENBORO, NC, 28320		