

INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
www.nclabor.com/elevator.htm  
919-807-2770

Report Number <b>15187-36-3074</b> State Number <b>17516</b>
-----------------------------------------------------------------------

EQUIPMENT INSPECTED

State Number: <b>17516</b>	Type of Unit: Passenger	Floor to Floor: B to 2
Capacity: 2500	Manuf: OTIS	Speed: 100
Landings: 3	Installed: 07/21/1998	Rope Size:
Volts: 208	Complied: 07/21/1998	Entrances: 1
OWNER	OCCUPANT	
B D DIAGNOSTICS	B D DIAGNOSTICS	
780 PLANTATION DR	780 PLANTATION DR	
BURLINGTON, NC, 27215	BURLINGTON, NC, 27215	

INSPECTION INFORMATION

Inspection Date 07/06/2015	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	---------------------------	--------------------

1

VIOLATIONS

none found

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: DEVIE INGOLD 336-222-9707

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

B D DIAGNOSTICS  
780 PLANTATION DR  
BURLINGTON, NC, 27215