



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
15189-48-2734
State Number
20869

EQUIPMENT INSPECTED

State Number: 20869	Type of Unit: Passenger	Floor to Floor: 1 to 4
Capacity: 2500	Manuf: OTIS	Speed: 100
Landings: 4	Installed: 02/04/2003	Rope Size: 0
Volts: 208	Complied: 02/04/2003	Entrances: 1

OWNER

1769 HORBORAGE CONDO
1769 HORBORAGE DR.
OCEAN ISLE, NC, 28469

OCCUPANT

1769 HORBORAGE CONDO
1769 HORBORAGE DRIVE
OCEAN ISLE, NC, 28469

INSPECTION INFORMATION

Inspection Date 07/08/2015	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK
-------------------------------	----------------------------	---------------------------------	--------------------------	---------------------

10

VIOLATIONS

8.6.4.8.2 Remove all materials from machine room (machinery space) not pertaining to the maintenance or operation of the elevator(s). [2ND. YR.]

Items must be corrected by: 08/07/2015

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: UNAVAILABLE

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

1769 HORBORAGE CONDO
1769 HORBORAGE DR.
OCEAN ISLE, NC, 28469