

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 15190-16-1791 State Number H1969

EQUIPMENT INSPECTED					
State Number: H1969 Capacity: 750	Type of Unit: I Manuf: TKE		Floor to Floor: 1 t Speed: 12	o 2	
Landings: 2	Installed: 04/23	3/2008	Rope Size: 0		
Volts: 120	Complied: 04/2	23/2008	Entrances: 2		
OWNER		OCCUPANT			
SECOND BAPTIST CHURCH		SECOND BAPTIST CHURCH			
2516 HWY 264 WEST		2516 HWY 264 WEST			
WASHINGTON, NC, 27889		WASHINGTON, NC, 27889			
	INS	PECTION INFORMATION			
Inspection Date 07/09/2015	Type Inspection Routine	Certificate Status Re-issued	Inspector 16 - Moore	County BEAUFORT	
		VIOLATIONS			
/a No violations	s found				
tify the Elevator Bureau in writing mplainace with current codes.	g on Corrected Violations Form w	then the following corrections have	e been made in order to brin	ng your equipment into	
Tiolations pointed out to: Lisa / Office Manager				Inspector	
To		ling address please call: 919-733-			
THIS IS NOT AN	n invoice will be mailed to:	SECOND BAPTIST CHUR 2516 HWY 264 WEST WASHINGTON NC 27889	СН		