

THIS IS NOT AN INVOICE

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 15209-36-1646 State Number 25341

1

| EQUIPMENT INSPECTED | | | | | | |
|----------------------------|-------------------|---|---|---------------------------|------------------------|--|
| State Number: 25341 Type | | Type of Unit: | of Unit: Passenger Floor to Fl | | to 3 | |
| Capacity: 2500 Manuf: SCH | | NDLER | Speed: 100 | | | |
| Landings: 3 Installed: 04 | | 15/2008 | Rope Size: | | | |
| Volts: 208 Complied: | | | Entrances: 1 | | | |
| OWNER | | OCCUPANT | | | | |
| ETHAN POINTE APARTMENTS | | | ETHAN POINT APARTMENTS | | | |
| 2978 ETHAN POINTE DRIVE | | | 1176 KIRKPATRICK ROAD | | | |
| BURLINGTON, NC, 27215 | | | BHRLINGTON, NC, 27215 | | | |
| | | Π | NSPECTION INFORMATION | | | |
| Inspection Date 07/28/2015 | | Type Inspection Routine | Certificate Status Re-issued | Inspector 36 - Kirkman | County ALAMANCE | |
| | | | VIOLATIONS | | | |
| 8.6.4.7.4 | Remove t | temove the oil from the pit floor and in sump pump. | | | | |
| 2.7.9.2 | | Place the a/c in proper working order | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | e corrected by: 0 | | | tor Name: BUILDING # 6 | | |
| | or Bureau in writ | | Eleva n when the following corrections h | | ng your equipment into | |

ETHAN POINTE APARTMENTS 2978 ETHAN POINTE DRIVE BURLINGTON, NC, 27215

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to: