



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
15215-8-0145
State Number
H2233

EQUIPMENT INSPECTED

State Number: H2233	Type of Unit: Hand Lift	Floor to Floor: 1 to 2
Capacity: 750	Manuf: SAVARIA	Speed: 14
Landings: 2	Installed: 08/23/2010	Rope Size:
Volts: 110	Complied:	Entrances: 1
OWNER		OCCUPANT
ANSON ANSON CO BOARD OF EDUCATION		ANSON ACADEMY
320 CAMDEN ROAD		321 CAMDEN ROAD
WADESBORO, NC, 28170		WADESBORO, NC, 28170

INSPECTION INFORMATION

Inspection Date 08/03/2015	Type Inspection Routine	Certificate Status Re-issued	Inspector 8 - Burris	County ANSON
-------------------------------	----------------------------	---------------------------------	-------------------------	-----------------

4

VIOLATIONS

A18.1 KEEP HOISTWAY DOOR & MANUAL LOWERING BOX ACCESS KEY ON PREMISES.

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: MELINDA HARRIS

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ANSON ANSON CO BOARD OF EDUCATION
320 CAMDEN ROAD
WADESBORO, NC, 28170