

THIS IS NOT AN

INVOICE

An invoice will be mailed to:

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 15215-8-139 State Number 7235

	EQUI	IPMENT INSPECTED		
State Number: 7235 Capacity: 1500 Landings: 2 Volts: 220	Type of Unit: Passenger Manuf: THYSSEN KRU Installed: 09/19/1972 Complied: 06/20/2000	JPP	Floor to Floor: 1 to 2 Speed: 75 Rope Size: Entrances: 1	
OWNER ANSON CO ADMIN BLDG 101 S. GREENE ST WADESBORO, NC, 28170		OCCUPANT HAMPTON B ALLEN LIBRARY 120 S GREENE ST WADESBORO, NC, 28170		
	INSPEC	CTION INFORMATION		
Inspection Date 08/03/2015	Type Inspection Routine	Certificate Status Re-issued	Inspector 8 - Burris	County ANSON
2.2.2.3 REMOVE OIL & WATE	R FROM PIT & REINSTALL PIT	OIL CAN (CK PIT SUMP PUMP)		
2.2.2.3 REMOVE OIL & WATE	R FROM PIT & REINSTALL PIT			
2.2.2.3 REMOVE OIL & WATE			R ELEVATOR	
	/2015	OIL CAN (CK PIT SUMP PUMP) Elevator Name: PASSENGE		equipment into

ANSON CO ADMIN BLDG

101 S. GREENE ST WADESBORO, NC, 28170