



INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
15216-8-0419
State Number
10528

EQUIPMENT INSPECTED

State Number: 10528	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2500	Manuf: THYSSEN KRUPP	Speed: 100
Landings: 2	Installed: 05/24/1983	Rope Size:
Volts: 208	Complied: 05/24/1983	Entrances: 1
OWNER	OCCUPANT	
ANSON CO ADMIN BLDG	ANSON CO COURTHOUSE	
101 S.GREENE ST	114 N GREENE ST	
WADESBORO, NC, 28170	WADESBORO, NC, 28170	

INSPECTION INFORMATION

Inspection Date	Type Inspection	Certificate Status	Inspector	County	
08/04/2015	Routine	Re-issued	8 - Burris	ANSON	4

VIOLATIONS

8.11.1.2 PERFORM ANNUAL PRESSURE RELIEF VALVE TEST

Items must be corrected by: 09/03/2015

Elevator Name: VISITOR ELEVATOR

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: WINDELL WILLIANSON

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ANSON CO ADMIN BLDG
101 S.GREENE ST
WADESBORO, NC, 28170