



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
15216-8-3022
State Number
H2078

EQUIPMENT INSPECTED

State Number: **H2078**

Capacity: 750

Landings: 2

Volts: 120

Type of Unit: Hand Lift

Manuf: SAVARIA

Installed: 03/04/2009

Complied: 03/04/2009

Floor to Floor: 1 to 1

Speed: 8

Rope Size:

Entrances: 2

OWNER

ANSON COUNTY GOVERNMENT

101 S GREENE STREET

WADESBORO, NC, 28170

OCCUPANT

ANSON COUNTY ADMIN OFB

101 S GREENE STREET

WADESBORO, NC, 28170

INSPECTION INFORMATION

Inspection Date
08/04/2015

Type Inspection
Routine

Certificate Status
Re-issued

Inspector
8 - Burris

County
ANSON

4

VIOLATIONS

NONE

Elevator Name: 1ST FLOOR LIFT

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: WENDELL WILLIAMSON

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ANSON COUNTY GOVERNMENT
101 S GREENE STREET
WADESBORO, NC, 28170