



INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
15231-48-2861
State Number
23725

EQUIPMENT INSPECTED

State Number: 23725	Type of Unit: Passenger	Floor to Floor: 1 to 4
Capacity: 2500	Manuf: THYSSEN KRUPP	Speed: 50
Landings: 4	Installed: 02/08/2006	Rope Size: .
Volts: 230	Complied:	Entrances: 1
OWNER	OCCUPANT	
OCEAN WALK HOA	OCEAN WALK CONDO #2	
C/O GO PROPERTY MGMT-G OWEN	105 SE 58TH ST	
WILMINGTON, NC, 28405	OAK ISLAND, NC, 28465	

INSPECTION INFORMATION

Inspection Date 08/19/2015	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK
-------------------------------	----------------------------	---------------------------------	--------------------------	---------------------

10

VIOLATIONS

2.2.2.4	Put the sump pump in proper working order.
8.6.4.7.4	Remove the water from the pit floor.
2.2.5.1	Put the pit lights in proper working order.
2.7.5.1	Put the machine room lights in working order.
8.6.4.9	Clean the elevator car top.
8.6.4.13.1[k]	Properly maintain door closers, where required. [REPAIR MR DOOR TO CLOSE AND LOCK ON ITS OWN]
2.27.1.1.2	Put the in car emergency telephone in proper working order.
2.27.3.1	Put the Phase I fire service feature in proper working order. [INOPERATIVE]

Items must be corrected by: 09/18/2015

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: UNAVAILABLE

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

OCEAN WALK HOA
C/O GO PROPERTY MGMT-G OWEN
WILMINGTON, NC, 28405