

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 15232-60-4010 State Number 21513

6

		EQUI	IPMENT INSPECTED		
State Num	nber: <b>21513</b>	Type of Unit: Passenger		Floor to Floor: 1 to 3	
Capacity:	2500	Manuf: OTIS		Speed: 125	
Landings: 3		Installed: 08/06/200	3	Rope Size: 0	
Volts: 208		Complied: 08/12/2003		Entrances: 1	
OWNER			OCCUPANT		
BANNER ELK PRESBYTERIAN			BANNER ELK PRESE	BYTERIAN	
PO BOX 158			420 COLLEGE DRIVE		
BANNER ELK, NC, 28604			BANNER ELK, NC, 2	8604	
		INSPEC	CTION INFORMATION		
Inspection Date 08/20/2015		Type Inspection Routine	Certificate Status Re-issued	Inspector 60 - Kircher	County AVERY
			VIOLATIONS		
8.6.5.16.5	( Overspeed valve shall l	be tested and resealed) If seal is brok	en or altered the overspeed valve	e shall be resealed after successf	ful test.
2.14.7.4					
3.6.1.2.1 Provide a written maintenance program.					

Items must be corrected by: 08/30/2015

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainace with current codes.

Violations pointed out to: Banner Elk Presbyterian 828-898-5406 Inspector \_\_\_\_\_

To make changes to the invoice mailing address please call: 919-733-0372

THIS IS NOT AN INVOICE

BANNER ELK PRESBYTERIAN

An invoice will be mailed to: PO BOX 158

 $BANNER\;ELK,\,NC,\,28604$