

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 15261-54-575 State Number 8543

8

		EQUIPM	ENT INSPECTED		
State Number: 8543		Type of Unit: Freight		Floor to Floor: 1 to 2	
Capacity:	12000	Manuf: SOUTHERN		Speed: 100	
• •		Installed: 02/03/1976		Rope Size:	
Volts: 480		Complied: 02/14/2000		Entrances: 1	
OWNER			OCCUPANT		
PERDUE INC.			PERDUE FARMS IN	C	
PO BOX 1537			HWY 308 WEST		
SALISBU	URY, MD, 21802		LEWISTON, NC, 278	49	
		INSPECTIO	ON INFORMATION		
Inspection Date 09/18/2015		Type Inspection Routine	Certificate Status Not Issued	Inspector 54 - Green	County BERTIE
		VI	OLATIONS		
	Properly document Provide an oil use Remove the oil from Empty the drain between Provide a class "A Provide the approximate Provide the approximate Provide the annual Provide clear according and cand Pulleys Replace or repair COVER CAR TO REPAIR IN CAR REPLACE 2ND	om the pit floor. ABC" fire extinguisher in the machine room or opriate test tag. the damaged car gate. al relief valve and system pressure test. ess to the machine room. YELLOW CLEARAN ar-door or gate mechanical and electrical compaRE CORRODED the damaged vision panels. 1ST LANDING	control space convenient to th NCE LINE onents shall be maintained to o	e access door.	on. LOWER CHAIN
Notify the I complainac Violations I	ee with current code pointed out to: MIK	writing on Corrected Violations Form when the s. XE HARDY 252 348 4360 To make changes to the invoice mailing add PH		Inspector	