

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 15300-36-0133 State Number 3044

1

	E	QUIPMENT INSPECTED			
State Number: 3044	Type of Unit: Passenger		Floor to Floor: 1 t	Floor to Floor: 1 to 2	
Capacity: 1000	Manuf: MONARCH		Speed: 75	Speed: 75	
Landings: 2	Installed: 08/25/1957		Rope Size:	Rope Size:	
Volts: 208	Complied: 08/25/	1957	Entrances: 1		
OWNER		OCCUPANT			
FIRST CHRISTIAN CHURCH					
PO BOX 1678	415 S CHURCH ST				
BURLINGTON, NC, 27215		BURLINGTON, NC, 27215			
	INS	SPECTION INFORMATION			
Inspection Date 10/27/2015	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE	
		VIOLATIONS			
none found					
otify the Elevator Bureau in wri	iting on Corrected Violations Form v	when the following corrections h	nave been made in order to bri	ng your equipment into	
iolations pointed out to: office					
	To make changes to the invoice ma				
THIS IS NOT AN INVOICE	An invoice will be mailed to:	FIRST CHRISTIAN CHU PO BOX 1678 BURLINGTON NC 277			