

THIS IS NOT AN

INVOICE

An invoice will be mailed to:

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 15345-7-5395 State Number 4320

EQUII	PMENT INSPECTED		
Type of Unit: Passenge	er	Floor to Floor: 1 to 3	
Manuf: SOUTHERN		Speed: 50	
Installed: 02/27/1962		Rope Size:	
Complied: 04/12/2000		Entrances: 1	
О	CCUPANT		
Q	UIET COUNTRY AMISH FUR	N.	
109 E MAIN ST			
W	VEST JEFFERSON, NC, 28694		
INSPEC	TION INFORMATION		
Type Inspection Routine	Certificate Status Re-issued	Inspector 7 - Hoffman	County ASHE
	VIOLATIONS		
1/10/2016			
	Type of Unit: Passenge Manuf: SOUTHERN Installed: 02/27/1962 Complied: 04/12/2000 Q 10 W INSPEC Type Inspection Routine	Type of Unit: Passenger Manuf: SOUTHERN Installed: 02/27/1962 Complied: 04/12/2000 OCCUPANT QUIET COUNTRY AMISH FUR 109 E MAIN ST WEST JEFFERSON, NC, 28694 INSPECTION INFORMATION Type Inspection Routine Certificate Status Re-issued VIOLATIONS DRM THE ANNUAL RELIEF VALVE TEST	Type of Unit: Passenger Floor to Floor: 1 to 3 Manuf: SOUTHERN Speed: 50 Installed: 02/27/1962 Rope Size: Complied: 04/12/2000 Entrances: 1 OCCUPANT QUIET COUNTRY AMISH FURN. 109 E MAIN ST WEST JEFFERSON, NC, 28694 INSPECTION INFORMATION Type Inspection Certificate Status Inspector 7 - Hoffman VIOLATIONS ORM THE ANNUAL RELIEF VALVE TEST

JACK BARR 201 MEADOW RIDGE DR. JEFFERSON, NC, 28640