

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 15348-7-4982 State Number 29516

	ΕÇ	UIPMENT INSPECTED		
State Number: 29516	Type of Unit: Pa Manuf: OTIS	ssenger	Floor to Floor: 1 to 3 Speed: 100	
Capacity: 3500 Manuf: OTIS Landings: 3 Installed: 08/19/2014 Volts: 230 Complied: 08/19/2014		2014	Rope Size: Entrances: 1	
OWNER	•	OCCUPANT		
WEST JEFFERSON FIRST E	BAPTIST CHURCH		SON BAPTIST CHURCH	
08 W SECOND STREET		08 W SECOND STREET		
WEST JEFFERSON, NC, 28694 WEST JEFFERSON, NC, 28694		SON, NC, 28694		
	INSF	ECTION INFORMATION		
Inspection Date 12/14/2015	Type Inspection Routine	Certificate Status Re-issued	Inspector 7 - Hoffman	County ASHE 5
		VIOLATIONS		
NONE				
Notify the Elevator Bureau in w complainace with current codes	rriting on Corrected Violations Form wh.	nen the following corrections have	been made in order to bring your e	quipment into
Violations pointed out to: 1ST.			Inspector	
	372			
THIS IS NOT AN INVOICE	An invoice will be mailed to:	WEST JEFFERSON FIRST BAPTIST CHURCH 08 W SECOND STREET WEST JEFFERSON, NC, 28694		