

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 15349-54-0671 State Number 8543

8

	EQU	IPMENT INSPECTED			
State Number: 8543	Type of Unit: Freigh	ht	Floor to Floor: 1 to 2		
Capacity: 12000	Manuf: SOUTHER!	N	Speed: 100		
Landings: 2	Installed: 02/03/197	6	Rope Size:		
Volts: 480	Complied: 02/14/20	00	Entrances: 1		
OWNER		OCCUPANT			
PERDUE INC.		PERDUE FARMS INC			
PO BOX 1537		HWY 308 WEST			
SALISBURY, MD, 21802		LEWISTON, NC, 2784	LEWISTON, NC, 27849		
	INSPE	CTION INFORMATION			
Inspection Date 12/15/2015	Type Inspection Compliance	Certificate Status Not Issued	Inspector 54 - Green	County BERTIE	
		VIOLATIONS			
complainace with current code		n the following corrections have be			
Violations pointed out to: MII			Inspector		
THE IC NOT AN	To make changes to the invoice mailing	To make changes to the invoice mailing address please call: 919-733-0372			
THIS IS NOT AN INVOICE	An invoice will be mailed to:	PERDUE INC. PO BOX 1537 SALISBURY, MD, 21802			