

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 15352-36-5023 State Number H822

	EQU	JIPMENT INSPECTED		
tate Number: H822 Type of Unit: Han-		d Lift Floor to Floor: 1 to 2		2
Capacity: 350	Manuf: BRUNO Installed: 10/03/1997		Speed: 20	
Landings: 2			Rope Size:	
Volts: 110	Complied: 10/03/19	997	Entrances: 2	
OWNER		OCCUPANT		
RANDOLPH ARTS GUILD	RANDOLPH ARTS GUILD			
125 SUNSET AVE	125 SUNSET AVE ASHEBORO, NC, 27203			
ASHEBORO, NC, 27203				
	INSPE	ECTION INFORMATION		
Inspection Date 12/18/2015	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County RANDOLPH 7
		VIOLATIONS		
None found				
Elevator Name: HANDICA	P LIFT			
Notify the Elevator Bureau in wr complainace with current codes.	iting on Corrected Violations Form who	en the following corrections	have been made in order to brin	g your equipment into
Violations pointed out to: office			Inspector	
=				
	To make changes to the invoice mailing address please call: 919-733-0372			
THIS IS NOT AN INVOICE	An invoice will be mailed to:	RANDOLPH ARTS GU 125 SUNSET AVE ASHEBORO, NC, 2720	JILD	