

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 16013-36-2529 State Number 25634

EQUIPMENT INSPECTED						
State Number: 25634		Type of Unit: Freight		Floor to Floor: 1 to 2		
Capacity: 20000		Manuf: O	ΓIS	Speed: 50		
Landings: 2 Installed: 12/2:			12/22/2008	Rope Size:		
Volts: 480		Complied:		Entrances: 1		
OWNER		OCCUPANT				
MALT O MEAL		MALT O MEAL				
2525 BANK STREE	Γ	2525 BANK STREET				
ASHBORO, NC, 272	03	ASHBORO, NC, 27203				
			INSPECTION INFORMATION			
Inspection Date 01/13/2016	Ro	nspection utine	Certificate Status Re-issued	Inspector 36 - Kirkman	County RANDOLPH	
			VIOLATIONS			
5.1.21.1	Put the in car alarm be	II in working order				
2.27.1.1.2 Put the in car emergency telephone in proper working order.						
Items must be corre	ected by: 02/12/2016		Elevator Name: RTE BLDG LINE 1 & 2			
Notify the Elevator Bur	reau in writing on Correc	ted Violations For	m when the following corrections	have been made in order to b	ring your equipment into	

To make changes to the invoice mailing address please call: 919-733-0372

THIS IS NOT AN INVOICE

complainace with current codes.

Violations pointed out to: AL SPENCER 336.683.5506

An invoice will be mailed to: MALT O MEAL 2525 BANK STR

to: 2525 BANK STREET ASHBORO, NC, 27203 Inspector \_\_\_