

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 16032-36-1759 State Number 24169

1

	E	QUIPMENT INSPECTED			
State Number: 24169	Type of Unit: Pass	senger	Floor to Floor: 1 to 3		
Capacity: 2500	Manuf: THYSSEN KRUPP		Speed: 100		
Landings: 3	Installed: 09/20/2006		Rope Size: 0		
Volts: 208	Complied: 09/20/2006		Entrances: 1		
OWNER		OCCUPANT			
SNR 27 CEDAR RIDGE OWNE	ER LLC	CEDAR RIDGE RE	TIREMENT CENTER		
5885 MEADOWS RD STE 500		2680 MEBANE STR	2680 MEBANE STREET		
LAKE OSWEGO, OR, 97035		, 27215			
	INS	SPECTION INFORMATION			
Inspection Date 02/01/2016	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE	
		VIOLATIONS			
None foun					
Notify the Elevator Bureau in write omplainace with current codes.	ing on Corrected Violations Form v	when the following corrections l	have been made in order to bri	ng your equipment into	
violations pointed out to: RICK R	REECE 336-229-2002				
	To make changes to the invoice ma				
THIS IS NOT AN INVOICE	SNR 27 CEDAR RIDGE OWNER LLC 5885 MEADOWS RD STE 500 LAKE OSWEGO, OR, 97035				