

Violations pointed out to: Bob 336.278.2000

THIS IS NOT AN INVOICE

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 16046-36-5757 State Number 24196

1

		EQUIPMENT INSPECTED			
State Number: 24196	Type of Unit:	: Passenger	Floor to Floor: 1 to 2		
Capacity: 2000	Manuf: OTIS		Speed: 125		
Landings: 2	Installed: 03/07/2007		Rope Size: 0		
Volts: 208	Complied: 03/07/2007		Entrances: 1		
OWNER		OCCUPANT			
OAKS BUILDING (F)	OAKS BUILDING				
416 N WILLIAMSON AVE	416 N WILLIAMSON AVENUE				
ELON, NC, 27244	ELON, NC, 27244				
]	INSPECTION INFORMATION			
Inspection Date 02/15/2016	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE	
		VIOLATIONS			
Items must be corrected by: 03			Elevator Name: (CampusPolice/Security)		
Notify the Elevator Bureau in writing complainace with current codes.	ng on Corrected Violations For	m when the following corrections l	nave been made in order to brin	ng your equipment into	

Page 1 of 1

OAKS BUILDING (F) 416 N WILLIAMSON AVE

ELON, NC, 27244

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

Inspector __