

complainace with current codes.

THIS IS NOT AN

INVOICE

Violations pointed out to: Office,336-229-3550

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 16054-12-4965 State Number 10994

1

EQUIPMENT INSPECTED						
State Number: 10994 Capacity: 2500 Landings: 2 Volts: 460		Type of Unit: Passenger Manuf: THYSSEN KRUPP Installed: 02/14/1986 Complied: 02/14/1986			Floor to Floor: 1 to 2 Speed: 100 Rope Size: Entrances: 1	
OWNER BURLINGTON POLICE BLDG PO BOX 1358 BURLINGTON, NC, 27216		OCCUPANT BURLINGTON POLICE BLD 267 W FRONT ST BURLINGTON, NC, 27215				
			INSPECTION INF	ORMATION		
Inspection Date 02/23/2016		Type Inspection Routine			Inspector 63 - Yarbrough	County ALAMANCE
			VIOLATI			
2.26.1.4.1 8.6	Put the car t	op inspection station in pro icator inside elevator is not	per working order.			
Items must be corre	ected by: 03/24	4/2016				
Notify the Elevator Bure	eau in writing	on Corrected Violations Fo	orm when the follow	ing corrections h	ave been made in order to bri	ng your equipment into

To make changes to the invoice mailing address please call: 919-733-0372 BURLINGTON POLICE BLDG

An invoice will be mailed to: PO BOX

PO BOX 1358

Inspector ___

BURLINGTON, NC, 27216