

THIS IS NOT AN

INVOICE

An invoice will be mailed to:

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 16060-36-1273 State Number 24654

1

		EQUIPMENT INSPECTED		
State Number: 24654	Type of Unit: Passenger		Floor to Floor: 1 to 2	
Capacity: 2100	Manuf: THYSSEN KRUPP		Speed: 100	
Landings: 2	Installed: 04/18/2007		Rope Size: 0	
Volts: 208	Complied: 04/18/2007		Entrances: 1	
OWNER	OCCUPAN	T		
ELON UNIVERSITY	ACADEMIC VILLAGE BELK -TEACHING-LEARNING			
803 HAGGARD AVENUE	360 ANTIOCH ROAD			
BURLINGTON, NC, 27244	ELON, NC	, 27215		
		INSPECTION INFORMATION		
Inspection Date 02/29/2016	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
		VIOLATIONS		
8.6.4.13.1[1]	Properly maintain door restricto	rs, where required.		
8.6.4.13.1[1]	Properly maintain door restricto	rs, where required.		
8.6.4.13.1[1]  Items must be corrected by: (			Name: Teaching-Learning	
Items must be corrected by: (	03/30/2016			ing your equipment into

ELON UNIVERSITY

803 HAGGARD AVENUE BURLINGTON, NC, 27244