



INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**16063-16-1350**  
State Number  
**10891**

EQUIPMENT INSPECTED

State Number: <b>10891</b>	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2000	Manuf: OTIS	Speed: 75
Landings: 2	Installed: 02/16/1984	Rope Size: 0
Volts: 480	Complied: 11/03/2003	Entrances: 1
OWNER	OCCUPANT	
BEAUFORT COUNTY COMM COLLEGE	BEAUFORT CO COMMUNITY COLLEGE	
5337 US HWY 264 EAST	5337 HWY 264 EAST	
WASHINGTON, NC, 27889	WASHINGTON, NC, 27889	

INSPECTION INFORMATION

Inspection Date 03/03/2016	Type Inspection Routine	Certificate Status Re-issued	Inspector 16 - Moore	County BEAUFORT
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

7

VIOLATIONS

2.14.7.1.3 Put the in car emergency light in working order.

Items must be corrected by: 04/02/2016

Elevator Name: # 5 Bldg

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Melvin Lodge / Maintenance Chief

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

BEAUFORT COUNTY COMM COLLEGE  
5337 US HWY 264 EAST  
WASHINGTON, NC, 27889