



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
16063-16-1540
State Number
14964

EQUIPMENT INSPECTED

State Number: 14964	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2500	Manuf: US ELEVATOR	Speed: 100
Landings: 2	Installed: 04/02/1993	Rope Size: 0
Volts: 480	Complied: 04/02/1993	Entrances: 1
OWNER	OCCUPANT	
BEAUFORT COUNTY COMM COLLEGE	BEAUFORT COMMUNITY COLLEGE	
5337 US HWY 264 EAST	5337 HWY 264 EAST	
WASHINGTON, NC, 27889	WASHINGTON, NC, 27889	

INSPECTION INFORMATION

Inspection Date 03/03/2016	Type Inspection Routine	Certificate Status Re-issued	Inspector 16 - Moore	County BEAUFORT
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

7

VIOLATIONS

2.14.7.1.3 Put the in car emergency light in working order.

Items must be corrected by: 04/02/2016

Elevator Name: #1 Bldg

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Melvin Lodge / Maintenance Chief

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

BEAUFORT COUNTY COMM COLLEGE
5337 US HWY 264 EAST
WASHINGTON, NC, 27889