NCDOL NCDOL NA Department of later

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 16081-48-2976 State Number 22802

10

		EQUIPMENT INSPECTED			
State Number: 22802 Capacity: 3000 Landings: 4 Volts: 208	Manuf: THYSSI Installed: 05/10/	Type of Unit: Passenger Manuf: THYSSEN KRUPP Installed: 05/10/2005 Complied: 02/15/2007		Floor to Floor: 1 to 4 Speed: 125 Rope Size: Entrances: 1	
OWNER CAM P.O. BOX 8126 OCEAN ISLE BEACH, NC, 28469		OCCUPANT ISLANDER RESORT - BLDG. #62 124 VIA OLD SOUND BLVD OCEAN ISLE BEACH, NC, 28469			
	I	NSPECTION INFORMATION			
Inspection Date 03/21/2016	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK	
		VIOLATIONS			
	service feature in proper working o				
complainace with current codes.	iting on Corrected Violations Form	when the following corrections	_		
Violations pointed out to: UNA					
THIS IS NOT AN INVOICE	To make changes to the invoice n An invoice will be mailed to:	nailing address please call: 919-7 CAM P.O. BOX 8126 OCEAN ISLE BEACH,			