



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
16099-36-2133
State Number
16089

EQUIPMENT INSPECTED

State Number: 16089	Type of Unit: Passenger	Floor to Floor: B to 1F
Capacity: 2100	Manuf: THYSSEN KRUPP	Speed: 100
Landings: 3	Installed: 11/16/1995	Rope Size:
Volts: 208	Complied: 11/27/1995	Entrances: 2
OWNER	OCCUPANT	
ALAMANCE-BURLINGTON SCHOOL SYSTEM	EASTLAWN SCHOOL	
1712 VAUGHN RD	502 N GRAHAM HOPEDALE	
BURLINGTON, NC, 27215	BURLINGTON, NC, 27217	

INSPECTION INFORMATION

Inspection Date 04/08/2016	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	---------------------------	--------------------

VIOLATIONS

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Office

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ALAMANCE-BURLINGTON SCHOOL SYSTEM
1712 VAUGHN RD
BURLINGTON, NC, 27215