

THIS IS NOT AN

INVOICE

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 16103-48-5693 State Number 11693

EQUIPMENT INSPECTED					
State Number: 11693	Capacity: 2000 Manuf: KONE		Floor to Floor: G to 3 Speed: 125 Rope Size: .		
Capacity: 2000					
Landings: 4					
Volts: 0	Complied: 02	Complied: 02/19/1987			
OWNER	OCCUPANT				
WEST BEACH VILLA		WEST BEACH VILLA			
2714 W BEACH DRIVE 2714 W. BEACH DRIVE					
LONG BEACH, NC, 28461	LONG BEACH, NC, 28461				
	I	NSPECTION INFORMATION			
Inspection Date 04/12/2016	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK 1	
		VIOLATIONS			
	Put the pit lights in proper working o Clean the elevator pit.	rder.			
Items must be corrected b	y: 06/12/2016		Elevator Name: # 1		
Notify the Elevator Bureau in complainace with current code	writing on Corrected Violations Formes.	n when the following corrections	have been made in order to	bring your equipment into	
Violations pointed out to: UN	JAVAILABLE		Inspector		

WEST BEACH VILLA

2714 W BEACH DRIVE LONG BEACH, NC, 28461

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to: