



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**16118-16-596**  
State Number  
**N7.5**

EQUIPMENT INSPECTED

State Number: <b>N7.5</b>	Type of Unit: Freight	Floor to Floor: 1 to 4
Capacity: 2000	Manuf: OTIS	Speed: 100
Landings: 4	Installed: 06/05/1975	Rope Size: 1/2
Volts: 220	Complied: 06/05/1975	Entrances: 2

OWNER

MRS BLACKSTONE  
C/O PAMLICO PROPERTIES  
WASHINGTON, NC, 27889

OCCUPANT

THE RICH COMPANY  
147 W MAIN ST  
WASHINGTON, NC, 27889

INSPECTION INFORMATION

Inspection Date 04/27/2016	Type Inspection Routine	Certificate Status Re-issued	Inspector 16 - Moore	County BEAUFORT
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

7

VIOLATIONS

8.11.2.2.2 Perform the annual no load safety test

Items must be corrected by: 05/27/2016

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Shannon Blackstone / Manager

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

MRS BLACKSTONE  
C/O PAMLICO PROPERTIES  
WASHINGTON, NC, 27889