

Violations pointed out to: MIKE 919-564-0978

THIS IS NOT AN

INVOICE

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 16132-36-0595 State Number 13710

1

EQUIPMENT INSPECTED					
State Number: 13710		Type of Unit: Passenger		Floor to Floor: 1 to 3	
Capacity: 4000		Manuf: THYSSEN KRUPP		Speed: 80	
Landings: 3		Installed: 09/19/1991		Rope Size:	
Volts: 460		Complied: 09/19/1991		Entrances: 1	
OWNER			OCCUPANT		
LAB CORP		LAB CORP			
ATTN STEVE THACKER		1447 YORK CT			
BURLINGTON, NC, 27215		BURLINGTON, NC, 27215			
		Ι	INSPECTION INFORMATION		
Inspection Date 05/11/2016		Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
			VIOLATIONS		
5.1.21.1	Dut the in a	ear alarm ball in working order			
2.27.1.1.2	Put the in car alarm bell in working order. Put the in car emergency telephone in proper working order.				
Items must be co	orrected by: 06/	10/2016			
	Bureau in writir		m when the following corrections	have been made in order to brit	ng your equipment into

LAB CORP

ATTN STEVE THACKER BURLINGTON, NC, 27215

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

Inspector ___