NCDOL NCDOL

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 16144-48-418 State Number 23516

		EQUIPMENT INSPECTED			
State Number: 23516	ate Number: 23516 Type of Unit: Passenger		Floor to Floor: 1 to 3		
Capacity: 2100	Manuf: OTIS		Speed: 100		
Landings: 3	Installed: 02/22/2006		Rope Size: 0		
Volts: 208 Complied: 0.		02/22/2006 Entrances:		1	
OWNER		OCCUPANT			
COMMUNITY AASOCIATION MGMT.			VILLAS ON OSPREY RIDGE		
P.O. BOX 8126		174 CLUB HOUSE RD			
0CEAN ISLE BEACH, N	NC, 28469	SUNSET BEACH, NC, 28468			
	п	NSPECTION INFORMATION			
Inspection Date 05/23/2016	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK	10
		VIOLATIONS			
2.2.2.4 Pu	t the sump pump in proper working orde	er.			
	Remove the water from the pit floor.				

Items must be corrected by: 07/23/2016

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainace with current codes.

Violations pointed out to: UNAVAILABLE Inspector _____

To make changes to the invoice mailing address please call: 919-733-0372

THIS IS NOT AN INVOICE

2.27.1.1.2

COMMUNITY AASOCIATION MGMT.

An invoice will be mailed to: P.O. BOX 8126

Put the in car emergency telephone in proper working order.

0CEAN ISLE BEACH, NC, 28469