NCD DIA N.C. Department of Labor

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 16158-48-0695 State Number H1689

EQUIPMENT INSPECTED					
State Number: H1689 Type of Unit: Har		Hand Lift	Floor to Floor:	Floor to Floor: 1 to 2 Speed: 12 Rope Size: 0	
Capacity: 750	Manuf: ACCESS Installed: 03/13/2006		Speed: 12		
Landings: 2			Rope Size: 0		
Volts: 115 Complied: 03/20/2006			Entrances: 2		
OWNER OCCUPANT					
OCEAN RIDGE BEACH CLUI	UB OCEAN RIDGE ROAD 8 E MAIN STREET				
8 E MAIN STREET					
SUNSET BEACH, NC, 28468		SUNSET BEACH, NC, 28468			
	INS	PECTION INFORMATION			
Inspection Date 06/06/2016	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK	10
		VIOLATIONS			
Notify the Elevator Bureau in writ complainace with current codes.	ing on Corrected Violations Form w	then the following corrections	have been made in order to	bring your equipment into	
Violations pointed out to: UNAVAILABLE			Inspector		
	To make changes to the invoice mai				
THIS IS NOT AN	An invoice will be mailed to:	OCEAN RIDGE BEACH 8 E MAIN STREET SUNSET BEACH, NC, 2	H CLUB		