



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

### INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**16167-66-3393**  
State Number  
**966**

#### EQUIPMENT INSPECTED

State Number: <b>966</b>	Type of Unit: Passenger	Floor to Floor: B to 4
Capacity: 2000	Manuf: OTIS	Speed: 100
Landings: 5	Installed: 02/20/1948	Rope Size: 1/2
Volts: 220	Complied: 09/17/2003	Entrances: 1
OWNER		OCCUPANT
35 PATTON CONDO ASSOCIATION		35 PATTON CONDO ASSOCIATION
P.O.BOX 1021		35 PATTON AVE
ASHEVILLE, NC, 28802		ASHEVILLE, NC, 28801

#### INSPECTION INFORMATION

Inspection Date 06/15/2016	Type Inspection Routine	Certificate Status Re-issued	Inspector 66 - Pacitti	County BUNCOMBE	11 A
-------------------------------	----------------------------	---------------------------------	---------------------------	--------------------	------

#### VIOLATIONS

8.6.4.9	Clean the elevator car top.
2.14.1.5.1	secure em exit
NOTE	OIL LEAK NEEDS TO BE ADDRESS FROM HOISTMECHINE

Items must be corrected by: 08/15/2016

Elevator Name: ELEVATOR # 1

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainace with current codes.

Violations pointed out to: 828-691-7194 C

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

35 PATTON CONDO ASSOCIATION  
P.O.BOX 1021  
ASHEVILLE, NC, 28802