



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
16172-36-4036
State Number
15587

EQUIPMENT INSPECTED

State Number: 15587	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 4500	Manuf: THYSSEN KRUPP	Speed: 100
Landings: 2	Installed: 03/07/1995	Rope Size:
Volts: 480	Complied: 02/21/2002	Entrances: 1
OWNER	OCCUPANT	
KERNODLE CLINIC	KERNODLE CLINIC #3 RC	
1234 HUFFMAN MILL RD	1234 HUFFMAN MILL RD	
BURLINGTON, NC, 27215	BURLINGTON, NC, 27215	

INSPECTION INFORMATION

Inspection Date 06/20/2016	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	---------------------------	--------------------

1

VIOLATIONS

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: bill 336-0909

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

KERNODLE CLINIC
1234 HUFFMAN MILL RD
BURLINGTON, NC, 27215