



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
16179-36-455
State Number
9613

EQUIPMENT INSPECTED

State Number: 9613	Type of Unit: Freight	Floor to Floor: 1 to 2
Capacity: 10000	Manuf: SOUTHERN	Speed: 40
Landings: 2	Installed: 01/29/1980	Rope Size:
Volts: 440	Complied: 01/29/1980	Entrances: 2
OWNER	OCCUPANT	
ATLAS LIGHTING PRODUCTS INC	ATLAS LIGHTING PRODUCTS INC	
1406 SOUTH MEBANE STREET	1406 SOUTH MEBANE STREET	
BURLINGTON, NC, 27216	BURLINGTON, NC, 27215	

INSPECTION INFORMATION

Inspection Date 06/27/2016	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	---------------------------	--------------------

1

VIOLATIONS

8.6.5.5.2 Oil leakage collected from the cylinder packing gland shall not exceed 20 L (5 gal) before removal. The container shall be covered and shall not be permitted to overflow.

Items must be corrected by: 07/27/2016

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: JEFF 336-222-9258

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ATLAS LIGHTING PRODUCTS INC
1406 SOUTH MEBANE STREET
BURLINGTON, NC, 27216