



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
16179-36-5259
State Number
N1.47

EQUIPMENT INSPECTED

State Number: N1.47	Type of Unit: Freight	Floor to Floor: 1 to 2
Capacity: 2500	Manuf: PARK	Speed: 60
Landings: 2	Installed: 01/11/1911	Rope Size: 5/8
Volts: 550	Complied: 01/11/1911	Entrances: 1
OWNER	OCCUPANT	
SPANO YARNS	SPANO YARNS	
219 W HARDEN STREET	219 W HARDEN STREET	
GRAHAM, NC, 27253	GRAHAM, NC, 27253	

INSPECTION INFORMATION

Inspection Date 06/27/2016	Type Inspection Removed	Certificate Status Not Issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------	----------------------------------	---------------------------	--------------------

1

VIOLATIONS

Left elevator notification

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: n/a

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

SPANO YARNS
219 W HARDEN STREET
GRAHAM, NC, 27253