



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
16193-65-189
State Number
9311

EQUIPMENT INSPECTED

| | | |
|---------------------------|---------------------------|------------------------|
| State Number: 9311 | Type of Unit: Passenger | Floor to Floor: 1 to 2 |
| Capacity: 2100 | Manuf: THYSSEN KRUPP | Speed: 125 |
| Landings: 2 | Installed: 10/24/1979 | Rope Size: 0 |
| Volts: 240 | Complied: 10/24/1979 | Entrances: 1 |
| OWNER | OCCUPANT | |
| AVERY COUNTY SCHOOLS | NEWLAND ELEMENTARY SCHOOL | |
| 775 CRANBERRY STREET | 750 LINVILLE STREET | |
| NEWLAND, NC, 28657 | NEWLAND, NC, 28657 | |

INSPECTION INFORMATION

| | | | | |
|-------------------------------|----------------------------|---------------------------------|--------------------------|-----------------|
| Inspection Date 07/11/2016 | Type Inspection Routine | Certificate Status Re-issued | Inspector 65 - Kelley | County AVERY |
|-------------------------------|----------------------------|---------------------------------|--------------------------|-----------------|

6

VIOLATIONS

| | |
|------------|---|
| 2.14.7.1.3 | Put the in car emergency light in working order. |
| 8.11.3.2.1 | Perform the annual relief valve test |
| 8.6.1.6.5 | Provide the required fire extinguisher in the machine room. |
| 8.6 | Replace exhaust fan screen in machine room |

Items must be corrected by: 08/30/2020

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Darryl 828-387-1564

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

AVERY COUNTY SCHOOLS
775 CRANBERRY STREET
NEWLAND, NC, 28657