

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 16196-48-0035 State Number H2175

	EG	QUIPMENT INSPECTED		
State Number: <b>H2175</b> Capacity: 750 Landings: 2 Volts: 120	Type of Unit: F Manuf: TKE Installed: 11/12 Complied: 11/1	2/2009	Floor to Floor: 1 to 2 Speed: 20 Rope Size: Entrances: 2	
OWNER FIRST BAPTIST CHURCH 521 MARTIN LUTHER KING J BLADENBORO, NC, 28320	R ST	OCCUPANT FIRST BAPTIST CHURCH 521 MARTIN LUTHER KING JR ST BLADENBORO, NC, 28320		
	INS	PECTION INFORMATION		
Inspection Date 07/14/2016	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BLADEN
		VIOLATIONS		
Elevator Name: # 1				
Notify the Elevator Bureau in writi complainace with current codes.	ng on Corrected Violations Form w	then the following corrections have	been made in order to bring yo	our equipment into
Violations pointed out to: Mrs. Mo		Inspector		
THIS IS NOT AN	To make changes to the invoice mai An invoice will be mailed to:	ling address please call: 919-733-03 FIRST BAPTIST CHURCH 521 MARTIN LUTHER KING BLADENBORO, NC. 28320		