



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
16196-48-426
State Number
18887

EQUIPMENT INSPECTED

State Number: 18887	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2100	Manuf: SCHINDLER	Speed: 100
Landings: 2	Installed: 11/23/1999	Rope Size:
Volts: 208	Complied: 11/23/1999	Entrances: 1
OWNER	OCCUPANT	
BLADENBORO HISTORICAL SOCIETY	BLADENBORO HISTORICAL SOCIETY	
818 S MAIN	818 S MAIN	
BLADENBORO, NC, 28320	BLADENBORO, NC, 28320	

INSPECTION INFORMATION

Inspection Date 07/14/2016	Type Inspection Not Inspected	Certificate Status Not Issued	Inspector 48 - Martin	County BLADEN
-------------------------------	----------------------------------	----------------------------------	--------------------------	------------------

9

VIOLATIONS

Elevator Name: # 1

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: UNAVAILABLE

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

BLADENBORO HISTORICAL SOCIETY
818 S MAIN
BLADENBORO, NC, 28320