



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
16196-48-4773
State Number
15135

EQUIPMENT INSPECTED

State Number: 15135	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2500	Manuf: THYSSEN KRUPP	Speed: 100
Landings: 2	Installed: 01/06/1994	Rope Size:
Volts: 480	Complied: 01/06/1994	Entrances: 1
OWNER	OCCUPANT	
ELM TREE APARTMENTS	ELM TREE APTS FOR ELDERLY	
10759 HWY 701	U S HWY 701 BUSINESS	
CLARKTON, NC, 28433	CLARKTON, NC, 28433	

INSPECTION INFORMATION

Inspection Date 07/14/2016	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BLADEN
-------------------------------	----------------------------	---------------------------------	--------------------------	------------------

9

VIOLATIONS

8.6.4.7.4 Remove the water from the pit floor.

Items must be corrected by: 09/14/2016

Elevator Name: # 1

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: PHYLLIS STRICKLIN

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ELM TREE APARTMENTS
10759 HWY 701
CLARKTON, NC, 28433