NCDOL NCDOL NA Department of John

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 16203-48-5079 State Number 20636

		EQUIPMENT INSPECTED			
State Number: 20636	Type of Unit: Passenger		Floor to Floor: 1 to 2		
Capacity: 2500	Manuf: OTIS	Manuf: OTIS		Speed: 125	
Landings: 2	Installed: 04/05/2002		Rope Size:		
Volts: 480	Complied:		Entrances: 1		
OWNER		OCCUPAN	OCCUPANT		
BRUNSWICK CO OPERATI	ON SERVICES	BRUNSWICK CO COURTHOUSE # 2			
PO BOX 249		45 COURTHOUSE DR			
BOLIVIA, NC, 28422		BOLIVIA, NC, 28422			
		NSPECTION INFORMATION			
Inspection Date 07/21/2016	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK	
		VIOLATIONS			
5.1.21.1 Put the	in car alarm bell in working order.				
2.27.1.1.2 Put the	in car emergency telephone in proj	per working order.			
8.11.2.2.2 Perform	n the annual no load safety test				

Items must be corrected by: 09/21/2016

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainace with current codes.

Violations pointed out to: CHRIS LANCASTER Inspector _____

To make changes to the invoice mailing address please call: 919-733-0372

THIS IS NOT AN INVOICE

BRUNSWICK CO OPERATION SERVICES

An invoice will be mailed to: PO BOX 249

BOLIVIA, NC, 28422