



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
16204-36-1391
State Number
H1544

EQUIPMENT INSPECTED

State Number: H1544	Type of Unit: Hand Lift	Floor to Floor: 1 to 4
Capacity: 550	Manuf: GARAVENTA	Speed: 20
Landings: 4	Installed: 10/11/2004	Rope Size:
Volts: 220	Complied: 10/11/2004	Entrances: 2
OWNER	OCCUPANT	
ALAMANCE BURLINGTON SCHOOL	GROVE PARK ELEMENTARY	
1712 VAUGHN ROAD	141 TRAIL ONE	
BURLINGTON, NC, 27217	BURLINGTON, NC, 27215	

INSPECTION INFORMATION

Inspection Date 07/22/2016	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	---------------------------	--------------------

1

VIOLATIONS

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: office 336-570-6115

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ALAMANCE BURLINGTON SCHOOL
1712 VAUGHN ROAD
BURLINGTON, NC, 27217