## NCDOL NCDOL NA Department of John

THIS IS NOT AN

INVOICE

An invoice will be mailed to:

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 16208-48-3921 State Number 12790

10

		EQUIPMENT INSPECTED		
State Number: 12790 Type of Unit: Capacity: 2500 Manuf: OTIS Landings: 16 Installed: 05/0 Volts: 480 Complied: 06/ OWNER CAM PO BOX 8126 OCEAN ISLE BEACH, NC, 28469		Speed: 200 19/1988 Rope Size: 5/8		
		INSPECTION INFORMATION		
Inspection Date 07/26/2016	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK
		VIOLATIONS		
		king order. [CAR STUCK ON G I	LEVEL]	
8.6.4.9 Clean the car to 2.27.1.1.2 Put the in car er			LEVEL]	
8.6.4.9 Clean the car to 2.27.1.1.2 Put the in car er	p of all debris.  mergency telephone in proper work  tor machine room.		LEVEL] Elevator Nar	ne: # 1
8.6.4.9 Clean the car to 2.27.1.1.2 Put the in car er 8.6.4.8.1 Clean the elevator of the second of	p of all debris.  mergency telephone in proper work  tor machine room.		Elevator Nan	

CAM PO BOX 8126

OCEAN ISLE BEACH, NC, 28469