



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
16210-36-3079
State Number
29228

EQUIPMENT INSPECTED

State Number: 29228	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 3000	Manuf: OTIS	Speed: 100
Landings: 2	Installed: 06/24/2014	Rope Size:
Volts: 480	Complied: 06/24/2014	Entrances: 1

OWNER

CLOVER GARDEN SCHOOL
2454 ALTMAHAW UNION ROAD
BURLINGTON, NC, 27215

OCCUPANT

CLOVER GARDEN SCHOOL
2454 ALTMAHAW UNION ROAD
BURLINGTON, NC, 27215

INSPECTION INFORMATION

Inspection Date 07/28/2016	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	---------------------------	--------------------

1

VIOLATIONS

2.27.1.1.2 Put the in car emergency telephone in proper working order.

Items must be corrected by: 08/07/2016

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Mrs. Walker (336) 586-9440

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

CLOVER GARDEN SCHOOL
2454 ALTMAHAW UNION ROAD
BURLINGTON, NC, 27215