

THIS IS NOT AN

INVOICE

An invoice will be mailed to:

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 16214-36-5762 State Number 19643

1

		EQUIPMENT INSPECTED		
State Number: 19643	Type of Unit: Passenger Manuf: THYSSEN KRUPP Installed: 01/05/2001		Floor to Floor: 1 to 3 Speed: 100 Rope Size:	
Capacity: 2500				
Landings: 3				
Volts: 200	Complied: 01/05/2001		Entrances: 1	
OWNER		OCCUPANT		
B.C. PARKER REAL ESTATE		DELANEY CROSSING #2		
336-226-8411	2223 DELANEY DR			
GREENSBORO, NC, 27429		BURLINGTON, NC, 27215		
		INSPECTION INFORMATION		
Inspection Date 08/01/2016	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
		VIOLATIONS		
		VIOLATIONS		
Notify the Elevator Bureau in writi	ing on Corrected Violations For	m when the following corrections l	nave been made in order to br	ing your equipment into

336-226-8411

B.C. PARKER REAL ESTATE

GREENSBORO, NC, 27429